












Mar. 1/62
AB-1








Rudder Installation
Figure 201 (Sheet 2 of 2)

27-7-1
Page 205



30.02.27.108





SPANNER NUT INSTALLATION-TYPICAL

BAFFLING-TYPICAL


OUTBOARD BEARING - NO. 2 SLAT ONLY

22 02 27 225 B

Aug. 27/62
AB-2

Wing Leading Edge Flap and Slat Drive
Torque Tube Installation
Figure 201

27-9-4
Page 203



30 02 27 220

RUDDER CONTROL PACKAGE - RIGHT-HAND SIDE

RUDDER CONTROL PACKAGE - LEFT-HAND SIDE

Rudder Hydraulic Servo Control Valve
Installation
Figure 201

